

# Inspection Photos

9/18/2017

Operator: PETRO-CANADA RESOURCES (USA)  
INC - 72085

Location ID: 376781

Inspection Doc. Number: 682502569  
Adams County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085  
Location ID: 376781



**Photo 1:** Photo taken from pad location, facing south. Photo shows corners of the pad requiring reclamation work to be conducted.



**Photo 2:** Photo taken from the pad location, facing west. Portions of the road. Portions of the road where stormwater degradation evident requires additional reclamation and stabilization.





**Photo 5:** Photo taken from the well location. Photo shows vegetation at the well does not meet reclamation standards. .