

Inspection Photos
Location Name: Vessels Minerals Location
Location# 335664



Phot of temporary sound walls being installed on west end of location photo taken from the west near playground at Aspen Ridge School



Photo taken from the west from the playground fence line showing opening in the wall and open top tanks



Photo taken from the Aspen Ridge School playground fence line



Photo taken from the vessels Minerals



Photo of open top tank photo taken from the east behind tank facing west toward the Aspen Ridge School playground Approx 25 yards to the west of the fence line