

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2017

Submitted Date:

09/21/2017

Document Number:

674200224**FIELD INSPECTION FORM**

Loc ID 434375 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestonepr.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434369	WELL	DG	04/25/2017	LO	123-38121	Waste Connections 3B-29H-M168	WO
434370	WELL	DG	04/24/2017	LO	123-38122	Waste Connections 3A-29H-M168	WO
434371	WELL	DG	04/28/2017	LO	123-38123	Waste Connections 3D-29H-M168	WO
434372	WELL	DG	04/26/2017	LO	123-38124	Waste Connections 3C-29H-M168	WO
434373	WELL	DG	04/29/2017	LO	123-38125	Waste Connections 3E-29H-M168	WO
434374	WELL	DG	04/30/2017	LO	123-38126	Waste Connections 3G-29H-M168	WO
434378	WELL	DG	04/29/2017	LO	123-38129	Waste Connections 3F-29H-M168	WO

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	APPROX 32' SOUND WALLS SURROUND LOCATION FOR SOUND MITIGATION AND LIGHTING MITIGATION		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 434369	Type: WELL	API Number: 123-38121	Status: DG	Insp. Status: WO
Facility ID: 434370	Type: WELL	API Number: 123-38122	Status: DG	Insp. Status: WO
Facility ID: 434371	Type: WELL	API Number: 123-38123	Status: DG	Insp. Status: WO
Facility ID: 434372	Type: WELL	API Number: 123-38124	Status: DG	Insp. Status: WO
Facility ID: 434373	Type: WELL	API Number: 123-38125	Status: DG	Insp. Status: WO
Facility ID: 434374	Type: WELL	API Number: 123-38126	Status: DG	Insp. Status: WO
Facility ID: 434378	Type: WELL	API Number: 123-38129	Status: DG	Insp. Status: WO

Complaint

Comment: Complaint Received Sept 18, 2017

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 9-18-2017 Time 0800Hrs

Contacted by Complaint Specialist per Complaint Response forms

Date: 9-18-2017

Well Number#: Location #: 434375

Inspection Document #: 674200224

Nature of complaint: Noise

Field Inspector Actions:

On 9-18-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received over the weekend by the COGCC about noise occurring in the Erie area south of the Crestone Peak Resources, Waste Connection frac pad.

On 9-15-2017, I performed a complete site inspection of the Waste Connection location and the neighborhoods south of the frac pad. At the time of inspection, I observed Liberty Services performing frac operations on the location for Crestone Peak Resources. I reviewed location records, which did not show any abnormal frac operations at the time of the complaints. I also reviewed the 3rd party sound data and the town of Erie's sound data information which did not show any exceedance of noise levels.

All information reviewed and site inspection information were submitted to the COGCC for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Stimulation			
Stimulation Company: LIBERTY SERVICES		Stimulation Type: HYDRAULIC FRAC	
Observation:		Other:	
Maximum Casing Recorded:	PSI	Tubing:	
Surface:		Intermediate:	
Production:		Instantaneous Shut-In Pressure (ISIP)	
Bradenhead Psi:		Frac Flow Back:	Fluid: Gas:
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	
Ditches	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT