

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2017

Submitted Date:

09/22/2017

Document Number:

680401943**FIELD INSPECTION FORM**
 Loc ID 334173 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 600 TRAVIS STREET SUITE 300City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment                         |
|-----------------|--------------|----------------------------|---------------------------------|
| Snow, Karl      | 435-631-2207 | karls@paradoxresources.com |                                 |
| Nowak, Scott    |              | scottn@bogresources.com    | <a href="#">All Inspections</a> |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | <a href="#">Field Inspector</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 282794      | WELL | PR     | 04/20/2015  | GW         | 113-06205 | HC FED 31-31-45-14 | PR          |
| 282801      | WELL | PR     | 10/26/2006  | GW         | 113-06206 | HC FED 31-22-45-14 | PR          |

**General Comment:**

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Main   |       |  |
| comment:           |        |       |  |
| Corrective Action  |        | Date: |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action  |        | Date: |  |

Overall Good: ☒

|                      |                       |       |  |
|----------------------|-----------------------|-------|--|
| <b>Signs/Marker:</b> |                       |       |  |
| Type                 | OTHER                 |       |  |
| Comment:             | Sign on meter housing |       |  |
| Corrective Action:   |                       | Date: |  |
| Type                 | WELLHEAD              |       |  |
| Comment:             |                       |       |  |
| Corrective Action:   |                       | Date: |  |
| Type                 | TANK LABELS/PLACARDS  |       |  |
| Comment:             |                       |       |  |
| Corrective Action:   |                       | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | WELLHEAD    |       |  |
| Comment:           | Panel fence |       |  |
| Corrective Action: |             | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Horizontal Heated Separator | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Deadman # & Marked          | # 4 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

|                     |   |       |
|---------------------|---|-------|
| Type: Flow Line     | # 2   |       |
| Comment:            | 2 -3" risers next to seperators. Locked out/Tagged out. |       |
| Corrective Action:  |   | Date: |
| Type: Plunger Lift  | # 2   |       |
| Comment:            |   |       |
| Corrective Action:  |   | Date: |
| Type: Gas Meter Run | # 2   |       |
| Comment:            |   |       |
| Corrective Action:  |   | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER     | 2 | 400 BBLS | STEEL AST |         | 38.112011,-108.460637 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**Facility ID: 282794 Type: WELL API Number: 113-06205 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger liftCorrective Action: Date: Facility ID: 282801 Type: WELL API Number: 113-06206 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: Shut in 3/2016. No MIT on record.Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs   | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|-----------------|--------------------------|---------|
| Gravel           | Pass            | Compaction              | Pass                  |                 |                          |         |
| Berms            | Pass            | Gravel                  | Pass                  | Self Inspection | Pass                     |         |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT