

Final Reclamation and Stormwater Inspection

September 19, 2017

Operator: UNIOIL- 90950

API: 05-069-06196

Larimer County, CO

NESW Section 25 T6N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MACLOUGHAN #25-1
API: 05-069-06196



Photo 1. Photo taken from the western location, facing East. Does not appear that any reclamation activities have been performed since the previous inspection.



Photo 2. Photo taken from the southern location, facing North. Does not appear that any reclamation activities have been performed since the previous inspection.