

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2017

Submitted Date:

09/25/2017

Document Number:

666803695**FIELD INSPECTION FORM**
 Loc ID 335344 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett		COGCC.inspections@caerus oilandgas.com	All Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266682	WELL	PR	06/03/2003	GW	045-09167	BENZEL 25-10C (K25)	PR
266683	WELL	PR	08/26/2003	GW	045-09168	BENZEL 25-11 (K25)	PR
266684	WELL	PR	03/17/2003	GW	045-09169	BENZEL 25-7C (K25)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

3

Comment: Corrective Action: Date:

Type: Vertical Heated Separator

3

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment: Centralized battery						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

PaintCondition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS			
CONDENSATE		2	300 BBLS	STEEL AST			39.496360,-107.725994			
Comment:										

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 266682 Type: WELL API Number: 045-09167 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Facility ID: 266683 Type: WELL API Number: 045-09168 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Facility ID: 266684 Type: WELL API Number: 045-09169 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Rip Rap	Pass			
		Sediment Traps	Pass			
Ditches	Pass					
		Gravel	Pass			
Berms	Pass					
		Culverts	Pass			
Seeding	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT