



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#				corrective date
Type: Gas Meter Run	# 2				
Type: Plunger Lift	# 2				
Type: Horizontal Heated Separator	# 2				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		39.466748,-107.693372	

**Paint**

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 211580 Type: WELL API Number: 045-07341 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

**BradenHead**

Comment: No PSI change in tubing or casing, Fluid to surfce

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 258069 Type: WELL API Number: 045-07618 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Berms	Pass					
		Gravel	Pass			
Gravel	Pass					
		Ditches	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT