

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2017

Submitted Date:

09/25/2017

Document Number:

666803704

**FIELD INSPECTION FORM**

Loc ID 335481 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
Name of Operator: VANGUARD OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295388	WELL	PR	10/27/2008	GW	045-15738	JOLLEY 31D-20-691	PR
295989	WELL	PR	04/17/2012	GW	045-15873	JOLLEY 41C-20-691	PR
295990	WELL	PR	05/09/2013	GW	045-15872	JOLLEY 41B-20-691	PR
296011	WELL	PR	10/26/2008	GW	045-15875	JOLLEY 31B-20-691	PR
296012	WELL	PR	11/09/2008	GW	045-15874	JOLLEY 41D-20-691	PR

**General Comment:**

[Facilities on location ID 335173](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume	corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical unit		
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	295388	Type:	WELL	API Number:	045-15738	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	295989	Type:	WELL	API Number:	045-15873	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	295990	Type:	WELL	API Number:	045-15872	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	296011	Type:	WELL	API Number:	045-15875	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	296012	Type:	WELL	API Number:	045-15874	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Seeding	Pass					
		Gravel	Pass			
Gravel	Pass					
		Ditches	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT