

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2017

Submitted Date:

09/25/2017

Document Number:

689800306**FIELD INSPECTION FORM**Loc ID 313326 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: PO BOX 12359City: SPRING State: TX Zip: 77391**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Rowell, Cheryl	713-542-0648	Cheryl_Rowell@swn.com	Senior Regulatory Analyst

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287344	WELL	TA	01/24/2017	GW	081-07348	AMELIA 44-1	TA

General Comment:

Inspected FacilitiesFacility ID: 287344 Type: WELL API Number: 081-07348 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

Follow up to inspection from 7/18/2017 document number 689800061. All corrective actions have been met, risers have been marked for abandonment.

waldrone

09/25/2017