

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2017

Submitted Date:

09/25/2017

Document Number:

689800310**FIELD INSPECTION FORM**

Loc ID 313146 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: PO BOX 12359City: SPRING State: TX Zip: 77391**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Maneotis, Karen	970-620-6099	Karen_Maneotis@swn.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262674	WELL	TA	08/05/2013	GW	081-07079	WALKER 12-2	TA

General Comment:

Inspected Facilities

Facility ID: 262674

Type: WELL

API Number: 081-07079

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Follow up to inspection from 7/18/2017 document number 689800065. All corrective actions have been met.	waldrone	09/25/2017