

# Inspection Photos

9/25/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP  
# 47120

Location ID: 331104

Inspection Doc. Number: 682502596  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: KERR MCGEE OIL & GAS ONSHORE LP # 47120  
Location ID: 331104



**Photo 1:** Photo taken from the access road and country road intersection to the southwest of the location, facing southeast. Photo shows vehicle tracking BMPs are no longer in proper function condition and need maintenance.



**Photo 2:** Photo taken from the access road and country road intersection to the southwest of the location, facing south. Photo shows vehicle tracking BMPs are no longer in proper function condition and need maintenance.

Inspection Photos  
Operator: KERR MCGEE OIL & GAS ONSHORE LP # 47120  
Location ID: 331104



**Photo 1:** Photo taken north of the well location, facing south towards the well location. Photo shows all crop has been removed.