

Inspection Photos

9/25/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 318995

Inspection Doc. Number: 682502609
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID: 318995



Photo 1: Photo taken from the east end of the well location, facing west. Photo shows reclamation activities appear to have been conducted.