

**Inspection Photos**  
**Location Name: AMBUSH 44-22**  
**API: 05-001-09072**



**WELLHEAD SIGN AND UNUSED PIPE,  
EQUIPMENT RODS, PIPE**



**SOILED DIRT INSIDE PUMP JACK HOUSE  
AT MOTOR MOUNTS**

