

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2017

Submitted Date:

09/26/2017

Document Number:

666803709

FIELD INSPECTION FORM

Loc ID 417085 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417063	WELL	PR	12/16/2010	GW	045-19450	GGU Barge Federal 32A-32-691	PR
417068	WELL	PR	12/16/2010	GW	045-19451	GGU Barge Federal 32C-32-691	PR
417077	WELL	PR	01/11/2011	GW	045-19452	GGU Barge 22D-32-691	PR
417086	WELL	PR	01/11/2011	GW	045-19453	GGU Barge Federal 32D-32-691	PR
417088	WELL	PR	12/16/2010	GW	045-19454	GGU Barge 22A-32-691	PR
417089	WELL	PR	12/16/2010	GW	045-19455	GGU Barge Federal 32B-32-691	PR
417094	WELL	PR	12/16/2010	GW	045-19456	GGU Barge Federal 33D-32-691	PR
417095	WELL	PR	01/11/2011	GW	045-19457	GGU Barge 22B-32-691	PR
417099	WELL	PR	01/11/2011	GW	045-19458	GGU Barge 22C-32-691	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 9			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 9			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:		Chemical unit at wellhead		
Corrective Action:				Date:
Type: Gas Meter Run	# 0			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	0				,
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	100 BBLs	STEEL AST		39.485949,-107.578738	
Comment: Bradenheads plumbed to tank						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	500 BBLs	STEEL AST		39.486206,-107.578295	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	YES					
Comment: Bradenhead valves open						
Corrective Action:					Date:	
Flaring:						
Type						

Comment:		
Corrective Action:	Date:	

Inspected Facilities									
Facility ID:	417063	Type:	WELL	API Number:	045-19450	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	417068	Type:	WELL	API Number:	045-19451	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	417077	Type:	WELL	API Number:	045-19452	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	417086	Type:	WELL	API Number:	045-19453	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	417088	Type:	WELL	API Number:	045-19454	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	417089	Type:	WELL	API Number:	045-19455	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	417094	Type:	WELL	API Number:	045-19456	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	417095	Type:	WELL	API Number:	045-19457	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 417099 Type: WELL API Number: 045-19458 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Rip Rap	Pass			
Berms	Pass					
Gravel	Pass					
		Gravel	Pass			
		Check Dams	Pass			
		Sediment Traps	Pass			
Seeding	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT