

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/26/2017

Submitted Date:

09/26/2017

Document Number:

666803712**FIELD INSPECTION FORM**

Loc ID 418465	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				Findings: <u>20</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418650	WELL	PR	06/13/2011	GW	045-19794	GGU Federal 41A-29-691	PR
418651	WELL	PR	07/11/2011	GW	045-19795	GGU Federal 41D-29-691	PR
418652	WELL	PR	07/08/2011	GW	045-19796	GGU Jolley 44B-20-691	PR
418653	WELL	PR	07/08/2011	GW	045-19797	GGU Swanson 32C-29-691	PR
418654	WELL	PR	05/19/2011	GW	045-19798	GGU Federal 31A-29-691	PR
418655	WELL	PR	06/08/2011	GW	045-19799	GGU Federal 41B-29-691	PR
418656	WELL	PR	05/18/2011	GW	045-19800	GGU Federal 42C-29-691	PR
418657	WELL	PR	05/18/2011	GW	045-19801	GGU Swanson 32D-29-691	PR
418663	WELL	PR	07/11/2011	GW	045-19802	GGU Federal 31D-29-691	PR
418664	WELL	PR	06/10/2011	GW	045-19803	GGU Federal 42D-29-691	PR
418665	WELL	PR	05/18/2011	OG	045-19804	GGU Federal 31B-29-691	PR
418666	WELL	PR	07/11/2011	GW	045-19805	GGU Federal 34A-20-691	PR
418669	WELL	PR	06/10/2011	GW	045-19806	GGU Federal 41C-29-691	PR
418670	WELL	PR	07/08/2011	GW	045-19807	GGU Federal 31C-29-691	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

14

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

3

Comment: Trailer mounted

Corrective Action:

Date:

Type: Compressor

2

Comment: Trailer mounted

Corrective Action:

Date:

Type: Ancillary equipment

4

Comment: Chemical units at wellhead

Corrective Action:

Date:

Type: Horizontal Heated Separator

14

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLS	STEEL AST		39.503037,-107.574022
Comment:					
Corrective Action:					
Date:					

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	418650	Type:	WELL	API Number:	045-19794	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	418651	Type:	WELL	API Number:	045-19795	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	418652	Type:	WELL	API Number:	045-19796	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	418653	Type:	WELL	API Number:	045-19797	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	418654	Type:	WELL	API Number:	045-19798	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	418655	Type:	WELL	API Number:	045-19799	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	418656	Type:	WELL	API Number:	045-19800	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	418657	Type:	WELL	API Number:	045-19801	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID: 418663	Type: WELL	API Number: 045-19802	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 418664	Type: WELL	API Number: 045-19803	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 418665	Type: WELL	API Number: 045-19804	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 418666	Type: WELL	API Number: 045-19805	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 418669	Type: WELL	API Number: 045-19806	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 418670	Type: WELL	API Number: 045-19807	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Rip Rap	Pass			
Rip Rap	Pass					
		Culverts	Pass			
		Check Dams	Pass			
		Gravel	Pass			
Sediment Traps	Pass					
		Sediment Traps	Pass			
Gravel	Pass					
Ditches	Pass					
Seeding	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT