

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Horizontal Heated Separator	# 7			
Comment:				
Corrective Action:				Date:
Plunger Lift	# 7			
Comment:				
Corrective Action:				Date:
Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Ancillary equipment	# 3			
Comment:	Chemical unit at wellhead			
Corrective Action:				Date:
Gas Meter Run	# 0			
Comment:				
Corrective Action:				Date:

Tanks and Birms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	0				
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Birms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	0				,		
Comment:							
Corrective Action:				Date:			
Paint							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	4	200 BBLs	STEEL AST		39.507039,-107.584466		
Comment:							
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			
Venting:							
Yes/No	YES						
Comment:	Bradenhead valves open						
Corrective Action:					Date:		
Flaring:							
Type							
Comment:							
Corrective Action:					Date:		

Inspected Facilities										
Facility ID:	259105	Type:	WELL	API Number:	045-07684	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	268105	Type:	WELL	API Number:	045-09244	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	270265	Type:	WELL	API Number:	045-09506	Status:	PR	Insp. Status:	SI	
Idle Well										
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: _____					
Comment:	Last posted productions posted Jul 2017									
Corrective Action:							Date:			
Facility ID:	270266	Type:	WELL	API Number:	045-09507	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	276399	Type:	WELL	API Number:	045-10446	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	276400	Type:	WELL	API Number:	045-10445	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	276409	Type:	WELL	API Number:	045-10451	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Gravel	Pass					
		Rip Rap	Pass			
Ditches	Pass					
Berms	Pass					
		Gravel	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT