



Figure 2
Erickson Birckle P25-4JI -
Tank Battery
Facility Layout &
Analytical Results

Legend

- Soil Sample
- Groundwater Sample
- Former Crude Oil Tank
- Former Produced Water Tank
- Existing Equipment
- Secondary Containment
- Excavation Extent

Sample Location

B: benzene
T: toluene
E: ethylbenzene
X: xylenes
TPH: total petroleum hydrocarbons

Bold values exceed COGCC Table
910-1 allowable concentrations


Site Characteristics

Legal Location: NWNW, Sec 25, T3N R67W
County: Weld
Land Use: Non-Cropland
Topography: 0-3% Slopes
Run-Off Risk: Very low
Soil Type: Bankard sandy loam

REVISED	BY	COMMENT
9/20/2017	BJB	Figure 2

Apex Companies, LLC
beau.bergstrom@apexcoos.com
M:\Projects\Anadarko\DJ_Basin\Remediation\Erickson_Birckle_P25-4JI\Projects\Erickson_Birckle_P25-4JI_Fig2_dig_20170920.mxd

Access Road



Non-Cropland

0 8.5 17
Feet
1 inch = 17 feet

N