



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), dropseed (*Sporobolus sp.*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is sparse in portions of the northern and western fill slopes.



Photo 4: View of erosional channel forming within the western portion of the project area.