



**Photo 1: View of the eastern portion of the project area from the northeastern corner facing southward.**



**Photo 2: View of the northern portion of the project area from the northwestern corner facing eastward.**



**Photo 3: View of the northwestern edge of the project area. Large kochia plants will soon dry and become debris.**



**Photo 4: View of the western edge of the project area. Rilling is occurring here.**