

Construction and Stormwater Inspection

September 27, 2017

Operator: 8 NORTH LLC - #10575

Location ID: 452153

Weld County, CO

SWSE Section 29 T12N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Darlene East /29-N Pad
Location ID: 452153



Photo 1. Photo taken from the entrance of location, facing Northwest. Tracking pad devices have been installed at the entrance.



Photo 2. Photo taken from the southeastern location, facing East. Temporary BMP's (ditch and berm) have been installed.

Inspection Photos
Location Name: Darlene East /29-N Pad
Location ID: 452153



Photo 3. Photo taken from the southeast location, facing North. Temporary BMP's (ditch and berm) have been installed.



Photo 4. Photo taken from the northeastern location, facing West. Temporary BMP's (ditch and berm) have been installed. Appears topsoil has been temporarily stabilized and stored along the northern location.

Inspection Photos
Location Name: Darlene East /29-N Pad
Location ID: 452153



Photo 5. Photo taken from the northwest location, facing South. Temporary BMP's (ditch and berm) have been installed.



Photo 6. Photo taken from the northwest location, facing East. Appears topsoil stockpile has been temporarily stabilized as well as cut slope areas.