

Inspection Photos
Location Name: Critter Creek #12-08H
API: 05-123-33088



Photo 1: Location, looking SW



Photo 2: Wellhead, looking W



Inspection Photos
Location Name: Critter Creek #12-08H
API: 05-123-33088



Photo 3: Stenciling is for prior operator



Photo 4: Debris in treater house