

Inspection Photos
Location Name: South Shale Ridge 16-16
Location ID: 312605



Photo 1. Equipment has been disconnected and moved to edge of location.