

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2017

Submitted Date:

09/27/2017

Document Number:

666803717

FIELD INSPECTION FORM

Loc ID 323891 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

- 6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211109	WELL	PR	04/10/1997	GW	045-06868	DALEY 1	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Type: Ancillary equipment	# 3				
Comment:	Chemical units at pig station				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Pig Station	# 7				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		39.503469,-107.585128
Comment:	Bradenhead plumbed to tank				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	OTHER	STEEL AST		39.503639,-107.585101		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity) 250bbbs							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	YES						
Comment:	Bradenhead valves open						
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 211109 Type: WELL API Number: 045-06868 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			
Gravel	Pass					
Berms	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT