

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2017

Submitted Date:

09/28/2017

Document Number:

666803722**FIELD INSPECTION FORM**

Loc ID 335209 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291978	WELL	PR	10/01/2012	GW	045-14577	JOLLEY 21-3D	PR
291981	WELL	PR	09/10/2008	GW	045-14574	JOLLEY 21-2D	PR
300760	WELL	PR	07/19/2011	GW	045-17996	Jolley KP 322-21	PR
300761	WELL	PR	07/03/2013	GW	045-17997	JOLLEY KP 522-21	PR
300762	WELL	PR	09/06/2011	GW	045-17998	Jolley KP 32-21	PR
300763	WELL	PR	11/01/2011	GW	045-17999	Jolley KP 332-21	PR
300764	WELL	PR	06/30/2011	GW	045-18000	Jolley KP 432-21	PR
300765	WELL	PR	01/17/2012	GW	045-18001	Jolley KP 532-21	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical units at wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLs	STEEL AST		39.514041,-107.561083	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	YES					
Comment:	Bradenhead valves open					
Corrective Action:				Date:		
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	291978	Type:	WELL	API Number:	045-14577	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	291981	Type:	WELL	API Number:	045-14574	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300760	Type:	WELL	API Number:	045-17996	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300761	Type:	WELL	API Number:	045-17997	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300762	Type:	WELL	API Number:	045-17998	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300763	Type:	WELL	API Number:	045-17999	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300764	Type:	WELL	API Number:	045-18000	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300765	Type:	WELL	API Number:	045-18001	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Gravel	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT