

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401391165
Date Received:
08/30/2017

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Brian Dodek 7202256653 bdodek@bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684904069
Inspection Date: 08/18/2017 FIR Submit Date: 08/18/2017 FIR Status:

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 331350

Location Name: Peterson Number: 14-28 Pad County: WELD
Qtrqtr: SWS Sec: 28 Twp: 5N Range: 63W Meridian: 6
W
Latitude: 40.365440 Longitude: -104.448360

FACILITY - API Number: 05-123-00 Facility ID: 430054

Facility Name: North Platte Number: J-F-28HZ
Qtrqtr: SWS Sec: 28 Twp: 5N Range: 63W Meridian: 6
W
Latitude: 40.365440 Longitude: -104.448360

CORRECTIVE ACTIIONS:

1 CA# 93195

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/18/2017

Response: CA COMPLETED Date of Completion: 08/30/2017

The compressor skid was drained and a hotsy was called out to spray the unit down. All of the stained and impacted gravel surrounding the skid was removed. All valves, pipes, and fittings were secured.

Operator Comment: _____

COGCC Decision: Approved pending re-inspection

COGCC Representative: _____

2 CA# 93196

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/18/2017

Response: CA COMPLETED

Date of Completion: 08/30/2017

Operator Comment: The impacted gravel around the production tank load out was removed and all valves, pipes, and fittings were secured.

COGCC Decision: Approved pending re-inspection

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek

Signed: _____

Title: Environmental Manager

Date: 8/30/2017 6:00:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401391165	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files