

# Inspection Photos

9/28/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP  
- 47120

Location ID: 302889

Inspection Doc. Number: 682502613  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the southwest end of the former battery facility. Photo shows meter houses have been removed and area appears to have been re-seeded and crimped with straw for stabilization.