

Inspection Photos

9/28/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 318670

Inspection Doc. Number: 682502623

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 318670



Photo 1: Photo taken from the east end of the well location, facing west. Photo shows two (2) pipe risers still remaining at the location. Inspection doc. #682502155 and #675103864 required operator to remove risers in accordance to COGCC 1004.a reclamation requirements.



Photo 2: See comments under photo 1