

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/29/2017

Submitted Date:

10/02/2017

Document Number:

666803725**FIELD INSPECTION FORM**
 Loc ID 335053 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------------------------------|
| Knudson, Dwayne | 970-456-3335 | dknudson@ursaresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 269103 | WELL | SI | 01/01/2017 | GW | 045-09318 | CSF 21A-18-07-91 | SI |
| 279973 | WELL | PR | 05/01/2014 | GW | 045-11121 | CSF 13B-07-07-91 | PR |
| 284522 | WELL | PR | 03/01/2017 | GW | 045-12200 | CSF 23B-07-07-91 | PR |
| 284524 | WELL | AL | 09/06/2011 | LO | 045-12199 | CSF 14B-07-07-91 | AL |
| 284534 | WELL | PR | 05/01/2017 | GW | 045-12198 | CSF 11B-18-07-91 | PR |
| 285458 | WELL | DA | 08/12/2006 | DA | 045-12481 | CSF 21-18-7-91 | DA |
| 286171 | WELL | PR | 07/01/2017 | GW | 045-12619 | CSF 21C-18-07-91 | PR |

General Comment:

Action required items noted in previous inspection have been satisfied, Flowlines have been marked with paint, tagged out

Inspected Facilities

| | | | | |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>269103</u> | Type: <u>WELL</u> | API Number: <u>045-09318</u> | Status: <u>SI</u> | Insp. Status: <u>SI</u> |
| Facility ID: <u>279973</u> | Type: <u>WELL</u> | API Number: <u>045-11121</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>284522</u> | Type: <u>WELL</u> | API Number: <u>045-12200</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>284524</u> | Type: <u>WELL</u> | API Number: <u>045-12199</u> | Status: <u>AL</u> | Insp. Status: <u>AL</u> |
| Facility ID: <u>284534</u> | Type: <u>WELL</u> | API Number: <u>045-12198</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>285458</u> | Type: <u>WELL</u> | API Number: <u>045-12481</u> | Status: <u>DA</u> | Insp. Status: <u>DA</u> |
| Facility ID: <u>286171</u> | Type: <u>WELL</u> | API Number: <u>045-12619</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |