

Inspection Photos

9/28/2017

Operator: PDC ENERGY INC - 69175

Location ID: 330004

Inspection Doc. Number: 682502626

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 330004



Photo 1: Photo taken from the northeast end of the battery location, facing west. Photo shows stormwater erosion degrading the location.



Photo 2: Photo taken from the northeast end of the battery location, facing east. Photo shows stormwater erosion degrading the location.



Photo 3: Photo taken from the former battery location, facing north. Inspection doc. #675103866 noted that the meter sheds had been removed, but pipe riser equipment associated with the meter sheds still remain. Photo shows riser equipment has not been removed per the corrective actions.