

Inspection Photos

9/28/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 329551

Inspection Doc. Number: 682502637

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the former battery location, facing south. Previous inspections required operator to remove equipment (meter shed) and related equipment. Photo shows equipment has not been removed.