

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/29/2017

Submitted Date:

10/02/2017

Document Number:

688300369**FIELD INSPECTION FORM**
 Loc ID 443722 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator
Strickler, Robert		Robert.D.Strickler@conocophillips.com	All DJ Basin Inspections
Prasanna, Sonu	832-486-2299	sonu.prasanna@conocophillips.com	Regulatory Supervisor
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	All DJ Basin Inspections
Aldrich, Brian	307-240-1882	Brian.C.aldrich@conocophillips.com	Production

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443723	WELL	DG	07/01/2017	LO	005-07249	Prosper Farms 4-65 2-1 4AH	WO
443724	WELL	DG	07/01/2017	LO	005-07250	Prosper Farms 4-65 2-1 4CH	WO

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	signs at gates		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	855-595-8258	Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 443723 Type: WELL API Number: 005-07249 Status: DG Insp. Status: WOFacility ID: 443724 Type: WELL API Number: 005-07250 Status: DG Insp. Status: WO**BradenHead**Comment: Form 17 completed and submitted by operator.

4CH

Casing 1700 psi for 15 minutes (no plug in hole yet)

Bradehead, slight blow died immediately, 0 psi for 15 mintues

4AH

Casing and Bradenhead 0 psi for 15 minutes.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300391	Conoco Prosper Farms 4-65 2-1 4AH and 4CH	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4264604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4264604</a>