

- Ute 6 05-067-06117



Photo 1: Wellhead sign.

- Ute 6 05-067-06117



Photo 2: Labeled chemical tank.

- Ute 6 05-067-06117



**Photo 3: Area around wellhead cleaned up.**

- Ute 6 05-067-06117



**Photo 4: Wire spool and weeds removed from gas meter run.**

- Ute 6 05-067-06117



**Photo 5: Weeds removed from tank containment.**

- Ute 6 05-067-06117



**Photo 6: Erosion channel in cut slope repaired.**

- Ute 6 05-067-06117



**Photo 7: Waddles and terraces installed to stabilize cut slope.**

- Ute 6 05-067-06117



**Photo 8: Location overview.**