



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the norththeastern corner facing westward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4: View of diffuse knapweed (*Centaurea diffusa*) within the project area.



Photo 5: View of the western portion of the project area from the northwestern corner facing southward.



Photo 6: View of silt trap in the southwestern corner of the project area. This is almost full of sediment and will soon require maintenance.