

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2017

Submitted Date:

10/03/2017

Document Number:

689400364**FIELD INSPECTION FORM**Loc ID 334490 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------------------|---------------------------------|
| Laramie Energy | | cogccnotifications@laramie-energy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 285459 | WELL | PR | 03/05/2007 | GW | 077-09093 | VEGA UNIT 10-131 | PR |
| 286320 | WELL | PR | 08/27/2008 | GW | 077-09122 | VEGA UNIT 10-121 | PR |
| 286322 | WELL | PR | 06/20/2008 | GW | 077-09123 | VEGA UNIT 9-421 | PR |
| 286326 | WELL | PR | 04/04/2008 | GW | 077-09127 | VEGA UNIT 9-414 | PR |
| 286329 | WELL | PR | 06/06/2008 | GW | 077-09126 | VEGA UNIT 9-424 | PR |
| 286331 | WELL | PR | 08/01/2012 | GW | 077-09125 | VEGA UNIT 9-434 | PR |
| 286334 | WELL | PR | 03/29/2007 | GW | 077-09124 | VEGA UNIT 9-431 | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 400 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

Venting:

| | | | |
|--------|----|--|--|
| Yes/No | NO | | |
|--------|----|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 285459 | Type: | WELL | API Number: | 077-09093 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286320 | Type: | WELL | API Number: | 077-09122 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286322 | Type: | WELL | API Number: | 077-09123 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286326 | Type: | WELL | API Number: | 077-09127 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286329 | Type: | WELL | API Number: | 077-09126 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286331 | Type: | WELL | API Number: | 077-09125 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286334 | Type: | WELL | API Number: | 077-09124 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Could not do complete stormwater inspection due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT