

Location

Lease Road:			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	2-Gas meter runs on north side of treaters		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 228		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 2		

Comment:	2-100 bbl treaters with metal sheds		Date:	
Corrective Action:			Date:	
Type:	Vertical Separator	# 1		
Comment:	Vertical gas separator in north treater shed		Date:	
Corrective Action:			Date:	
Type:	Ancillary equipment	# 5		
Comment:	Electric panel, telemetry equipment, cathodic rectifier, chemical drum in metal shed, gas circ pump at battery		Date:	
Corrective Action:			Date:	
Type:	Deadman # & Marked	# 4		
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.843680,-102.127640
Comment:	Water tank is on north side of production tanks				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		38.843680,-102.127640
Comment:	4-Production tanks				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 207883 Type: WELL API Number: 017-06818 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for Arapahoe Unit \(170, 171, 172, 173, 174, 175\) 630' W @ 38.843680/-102.127640](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT