



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with antelope bitterbrush (*Purshia tridentata*), snakeweed (*Gutierrezia sarothrae*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4: View of silt trap in the northeastern portion of the project area that is nearly full of sediment and will soon require maintenance.



Photo 5: View of erosional channel approximately 18 inches wide and 10 inches deep, along the access road.



Photo 6: View of more erosional channels up to 12 inches deep, along the access road.



Photo 7: View of unmarked risers on the well pad.