

Final Reclamation and Stormwater Inspection

October 3, 2017

Operator: Blue Chip Oil Inc- 8840

API: 05-123-14512

Weld County, CO

NESE Section 25 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SLOAN #3
API: 05-123-14512



Photo 1. Photo taken of the Operator sign at location.



Photo 2. Photo taken from the battery location, facing South. Equipment still at location needs to be removed per Rule 1004.a.

Inspection Photos
Location Name: SLOAN #3
API: 05-123-14512



Photo 3. Photo taken from the battery location, facing Southeast. Equipment still at location needs to be removed per Rule 1004.a.



Photo 4. Photo taken from the battery location, facing Northwest. Equipment still at location needs to be removed per Rule 1004.a.

Inspection Photos
Location Name: SLOAN #3
API: 05-123-14512



Photo 5. Photo taken from the western battery location, facing Southeast. Did not observe any stormwater BMPs during the removal of equipment.



Photo 6. Photo taken from the approximate well location, facing West. Stockpile from mining operations is located on top of well location.

Inspection Photos
Location Name: SLOAN #3
API: 05-123-14512



Photo 7. Photo taken from the southern battery location, facing West. Comply with Rule 603.f. Russian thistle observed along the southern and northern battery location.



Photo 8. Photo taken from the northern battery location, facing West. Comply with Rule 603.f. Russian thistle observed along the southern and northern battery location.