

Inspection Photos
Location Name: HOLDERBY #1
Location# 05-013-06354



PHOTO FROM PREVIOUS INSPECTION



PHOTO FROM PREVIOUS INSPECTION

Inspection Photos
Location Name: HOLDERBY #1
Location# 05-013-06354



**SHARED TANK BATTERY TAKEN FROM THE SOUTH THIEF
HATCH AND BLOW DOWN VALVE CLOSED**



WELLHEAD TAKEN FROM THE SOUTH WEEDS AT WELLHEAD