

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2017

Submitted Date:

10/04/2017

Document Number:

688300410**FIELD INSPECTION FORM**

Loc ID 450811 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 49888Name of Operator: LARIO OIL & GAS COMPANYAddress: PO BOX 29City: DENVER State: CO Zip: 80201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Veillette, Christian	(303) 898-1770	christian@lario.net	VP Operations
Eastwood, Blair	(720) 457-6567	blair@lario.net	Production Technician
O'Shaughnessy, Mike	(303) 595-8083	mike@lario.net	President/CEO
Anderson, Christina		chris@lario.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450812	WELL	DG	07/10/2017		121-11068	Wakanda 3-42	PA

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 316-265-5611

Corrective Action: _____ Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 450812 Type: WELL API Number: 121-11068 Status: DG Insp. Status: PA**Cement**Cement ContractorContractor Name: QES

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 575-430, 50-0Cement Volume (sx): 75, 15Good Return During Job: YES

Cement Type: _____

Comment: No flowlines or equipment.
Pits not closed (need to evaporate water).

Corrective Action: _____

Date: _____

WorkoverComment: Codell Rig #3

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300411	Lario Wakanda 3-42 PA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4266310