



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with grasses, shrubs, and forbs such as Indian ricegrass (*Achnatherum hymenoides*), and rubber rabbitbrush (*Chrysothamnus nauseosus*) as well as weeds such as cheatgrass (*Bromus tectorum*).



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4: View of area in the eastern portion of the project area that is cleared of vegetation. This area needs to be revegetated, or a surface owner waiver needs to be obtained.



Photo 5: View of treated Canada thistles (*Cirsium arvense*) in the southeastern corner of the working area.



Photo 6: View of the southern edge of the working area near project facilities that is bordered by dead trees.



Photo 7: View of the northern edge of the working area that is bermed.



Photo 8: View of typical vegetation outside of the project area. Dense pinion juniper woodland and sparse understory vegetation.