

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401420590

Receive Date:

10/05/2017

Report taken by:

CARLOS LUJAN

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

### OPERATOR INFORMATION

Name of Operator: CAERUS PICEANCE LLC	Operator No: 10456	<b>Phone Numbers</b>
Address: 1001 17TH STREET #1600		
City: DENVER State: CO Zip: 80202		
Contact Person: Brett Middleton	Email: bmiddleton@caerusoilandgas.com	
		Phone: (970) 285.2739
		Mobile: (970) 987.4650

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 9307 Initial Form 27 Document #: 2315685

#### PURPOSE INFORMATION

- |  |   |
|--|---|
| <input type="checkbox"/> 901.e. Sensitive Area Determination                                       | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water                              |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure                             | <input checked="" type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation                            | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project   |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste                      | <input type="checkbox"/> Rule 906.c.: Director request  |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____  |

#### SITE INFORMATION

N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: PIT	Facility ID: 414395	API #: _____	County Name: GARFIELD
Facility Name: M23	Latitude: 39.680820	Longitude: -108.142235	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWSW	Sec: 23	Twp: 4S	Range: 96W Meridian: 6 Sensitive Area? Yes

#### SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use RANGELAND

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

#### Other Potential Receptors within 1/4 mile

According to COGCC GISonline mapping: one(1) stream and no (0) water wells within 1/4 mi of stor pit

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	within pit footprint	soil boring data

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

The northern quarter of the pit was excavated down to competent bedrock and the 4 side walls were excavated to the first set of south wells. (please see pit diagram). The pit bottom was not sampled due excavating to bedrock at 15 feet and pit bottom soil not being present. Excavated soils were stockpiled and sampled for clearance.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Grab samples were collected from the four side wall and from the two excavated stockpiles.

#### Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

no groundwater exists within the excavaed or sampled area.

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

no surface water impacts from occurred from this location.

### Additional Investigative Actions

☒ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

site is being excavated and resampled for clearance.

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 37

Number of soil samples exceeding 910-1 5

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 2100

### NA / ND

-- Highest concentration of TPH (mg/kg) 11000

-- Highest concentration of SAR 77

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 15

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 60'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

NA Highest concentration of Benzene (µg/l)

NA Highest concentration of Toluene (µg/l)

NA Highest concentration of Ethylbenzene (µg/l)

NA Highest concentration of Xylene (µg/l)

NA Highest concentration of Methane (mg/l)

### Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

Background for Arsenic was collected from this location As ranged from 3.4 to 5.8 mg/kg. As within the pit samples ranged from 2.7 to 7.3 mg/kg.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

After removal of the pit liner, a number of grab samples will be collected adequate to characterize the size and depth of the pit. Samples will be submitted for laboratory analysis of COGCC Table 910-1 constituents of concern. The location of the samples, and laboratory results will be provided in subsequent form submittals as previously described.

## REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes \_\_\_\_\_

### **SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Pit fluids will be removed using existing infrastructure associated with Encana's North Parachute water treatment and storage system. The liner will be pressure washed, and above liner solids will be recovered using hydrovac trucks and/or trash pumps.

Solids will be offloaded at the proposed transport staging site detailed in the attached Waste Management Plan. The liner will be removed and transported offsite for recycling/disposal. Offsite disposal records are available upon request.

### **REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

The northern quarter of the pit was excavated down to competent bedrock and the 4 side walls were excavated to the first set of south wells. (please see pit diagram). The pit bottom was not sampled due excavating to bedrock at 15 feet and pit bottom soil not being present. Excavated soils were stockpiled and sampled for clearance.

### **Soil Remediation Summary**

☐ In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

☒ Ex Situ

No \_\_\_\_\_ Excavate and offsite disposal

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_

Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_

Yes \_\_\_\_\_ Excavate and onsite remediation

Yes \_\_\_\_\_ Land Treatment

No \_\_\_\_\_ Bioremediation (or enhanced bioremediation)

No \_\_\_\_\_ Chemical oxidation

No \_\_\_\_\_ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

No \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

No \_\_\_\_\_ Chemical oxidation

No \_\_\_\_\_ Air sparge / Soil vapor extraction

No \_\_\_\_\_ Natural Attenuation

No \_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

No groundwater was present during and soil borings or excavation activities.

## REMEDATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:** ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other \_\_\_\_\_

**Report Type:** ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report  
☐ Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

excavated soils were mixed and used as backfill of the pit on this location.

Volume of E&P Waste (solid) in cubic yards 0

E&P waste (solid) description impacted soils below and in the side walls of the pit liner

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDATION COMPLETION REPORT

### REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? No

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? Yes

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The pit footprint occurs within the boundary of the location's working surface and will be backfilled and compacted. The 5 feet of excavated cover material was placed back over the excavated material and covered with gravel. The pit location is within the location pad footprint.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☒ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? Yes

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 09/19/2017

Date of commencement of Site Investigation. 09/22/2017

Date of completion of Site Investigation. 09/27/2017

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 09/19/2017

Date of completion of Remediation. 09/22/2017

### SITE RECLAMATION DATES

Date of commencement of Reclamation. 09/27/2017

Date of completion of Reclamation. 09/27/2017

### OPERATOR COMMENT

Attn: Carlos Lujan

Please see closure report for M23 Pit remediation completion

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Brett Middleton

Title: Sr. Env. Specialist

Submit Date: 10/05/2017

Email: bmiddleton@caerusoilandgas.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: CARLOS LUJAN

Date: 10/05/2017

Remediation Project Number: 9307

### COA Type

### Description

--	--

## Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

### Att Doc Num

### Name

401420590	FORM 27-SUPPLEMENTAL-SUBMITTED
401420626	FORM 27 (SUPPLEMENTAL)

Total Attach: 2 Files

## General Comments

### User Group

### Comment

### Comment Date

Environmental	Status of Pit Facility ID #414395 will be changed to CLOSED.	10/05/2017
Environmental	Closure of the Remediation Project has been approved. The remediation project REM #9307 will be closed. No Further Action is Required regarding the closure of Pit Facility ID #414395.	10/05/2017

Total: 2 comment(s)