

Inspection Photos

Location Name: Schank J 35-20, 35-21, 35-6

API #: 05-123-26252,05-123-26443,05-123-19202

Location ID: 336706



Schank J 35-20 wellhead looking north



Schank J 35-21 wellhead looking north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Schank J 35-20, 35-21, 35-6

API #: 05-123-26252,05-123-26443,05-123-19202

Location ID: 336706



Schank J 35-6 wellhead looking north



Battery looking west



Inspection Photos

Location Name: Schank J 35-20, 35-21, 35-6

API #: 05-123-26252,05-123-26443,05-123-19202

Location ID: 336706



Location washing out from northeast edge of tank battery and running along the east side of tank battery, discharging sediment off of location



Actively growing weeds on location need to be controlled



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Schank J 35-20, 35-21, 35-6

API #: 05-123-26252,05-123-26443,05-123-19202

Location ID: 336706



2 unused/disconnected gas meter runs need to be removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources