

**Inspection Photos**  
**Location Name: Federal SP 32-14**  
**Location ID: 418429**



**Photo 1. Gravel has been added to area of erosion on pad surface and sediment trap maintained.**



**Photo 2. Cut slope appears to be the same as reported in inspection Doc#680200081.**