

Inspection Photos
Location Name: Coachman Pit 430542
Net collapse
10/5/2017



Pit looking Northeast



Pit looking East



**Deadman anchor dragged towards pit.
Looking NNW**



**Snowmelt standing water on pad, looking
east**