

# Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327102

Inspection Doc. Number: 682502649

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327102



**Photo 1:** Photo taken from the southeast end of the battery facility, facing west. Photo shows overview of the former battery location.



**Photo 2:** Photo taken from the southeast end of the battery facility, facing northwest. Photo shows overview of the former battery location.





**Photo 3:** Photo taken from the former battery location. Photo shows crop (corn) vegetation growth over the well location is stunted when compared to the adjacent reference area (see photo 4). 6 foot measuring stick for reference. Crop growth within the disturbance ranges from ~3-4 feet in height. Unable to find evidence that additional reclamation activities have been performed per corrective actions.



**Photo 4:** Photo taken from the adjacent reference area. Photo shows crop (corn) vegetation growth over the reference area. Crop in the disturbance areas are visibly stunted when compared to the reference. 6 foot measuring stick for reference. Crop growth within the reference ranges ~6 feet or greater.