

Inspection Photos

10/05/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323695

Inspection Doc. Number: 682502651

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast end of the former battery location. Previous inspections required operator to perform reclamation and return the disturbance area to its designated final land use. Adjacent reference area is Alfalfa crop. Photo shows no additional reclamation activities appear to have been conducted.



Photo 2: Photo taken from the northeast end of the former battery location, facing south. Photo shows overview of the battery location.



Photo 3: Photo taken from the former battery location. Photo shows inspector had tested the location to see if compaction concerns remains. Photo shows that the shovel was only able to penetrate the first couple of inches with ease. Compaction concerns remain.



Photo 4: Photo taken from the adjacent reference area. Inspector had tested the soil in the reference area to compare to the disturbance area. Inspector was able to penetrate ~10 inches of topsoil without difficulty.