

Inspection Photos

10/06/2017

Operator: MAGPIE OPERATING, INC - 52530

Location ID: 400749

Inspection Doc. Number: 682502689

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 400749



Photo 1: Photo taken from the northeast corner of the location, facing southwest. Photo shows reclamation in process.



Photo 2: Photo taken from the northeast corner of the location, facing west. Photo shows reclamation in process.

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 400749



Photo 3: Photo taken from the location. Photo shows reclamation in process.



Photo 4: Photo taken from the west end of the location, facing east. Photo shows reclamation in process.