

Inspection Photos

10/06/2017

Operator: MAGPIE OPERATING, INC - 52530

Location ID: 316981

Inspection Doc. Number: 682502691

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 316981



Photo 1: Photo taken from the east end of the well location. Photo shows utilities and gravel have been removed, area appears to have been reseeded. Please note, majority of green vegetation seen in photo is Canada thistle. This is a Colorado State Noxious weed and needs to be managed.



Photo 2: Photo taken from the north end of the well location. Photo shows Canada thistle on location.

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 316981



Photo 3: Photo taken from the access road, facing east. Photo shows access road has been re-contoured and re-graded per corrective actions. Canada this can be found throughout the entire access road, this needs to be managed.



Photo 4: Photo shows Canada thistle found on access road.