

**Inspection Photos**  
**Location Name: Dittmer KE Pad**  
**API: 05-123-43441**



**Photo 1: Location, looking S**



**Photo 2: Wellheads, looking NE**

Inspection Photos  
Location Name: Dittmer KE Pad  
API: 05-123-43441



Photo from prior inspection for comparison



Photo 3: No decal on produced water tank

**Inspection Photos**  
**Location Name: Dittmer KE Pad**  
**API: 05-123-43441**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil removed. Water is from fire control or precipitation event.**

Inspection Photos  
Location Name: Dittmer KE Pad  
API: 05-123-43441



Photo from prior inspection for comparison



Photo 5: Stained soil at truck loadout.

Inspection Photos  
Location Name: Dittmer KE Pad  
API: 05-123-43441



Photo from prior inspection for comparison



Photo 6: Stained soil at Wellheads on W side.