

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/13/2017

Submitted Date:

10/13/2017

Document Number:

679903179**FIELD INSPECTION FORM**

Loc ID 321704 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|-------------------|---------|
| Kennedy, Herschel | 719-767-8851 | hkennedy@cogc.com | |
| Elsom, Lee Ann | 281-891-1577 | lelsom@cogc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 207822 | WELL | PR | 12/01/1989 | OW | 017-06757 | ARAPAHOE UNIT 125 (41-36) | PR |

General Comment:

Location

| | | | |
|--------------------|---------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through farm ground | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|-------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Leas sign by unit | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|--|-------------|
| Emergency Contact Number: | | |
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------------------------------------------------------------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Metal panels around cathodic rectifier | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Chain link fence around location. Wire fence on north side of battery | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 4 | | |
| Comment: | Electric panel, cathodic rectifier, electric circ pump at tanks, propane tank by treaters, electric transfer pump and filter pots in metal shed by water tanks | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run on west side of treaters | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------------|-------------------------------------|-------|
| Type: Vertical Separator | # 2 | |
| Comment: | 2-100bbls treaters with metal sheds | |
| Corrective Action: | | Date: |
| Type: Pump Jack | # 1 | |
| Comment: | Sentry 160 | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|--------------------------------------------------|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 400 BBLS | STEEL AST | | 38.798780,-102.053290 |
| Comment: | 2-Tan production tanks on south side of location | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|----------------------------------------------------|----------|----------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 3 | 400 BBLS | FIBERGLASS AST | | 38.799090,-102.053720 |
| Comment: | 3-Blue water tanks on northwest corner of location | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|-------------------------------------------------------------------------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 207822 | Type: | WELL | API Number: | 017-06757 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Central tank battery for Arapahoe Unit (125, 129, 130) 850' NE @ 38.79878/-102.05329 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT